



YD7001-USB Properties



USB Properties


YD7001 -

7001D0013824

Ports

YD.Control	COM3
XpressNet	COM8
LocoNet	COM7



Firmware

YD7001 version	8.2.2	 Update YD7001
Latest version	8.2.2	

Factory defaults

Reset

YD7001-WiFi Props Properties





WiFi Props Properties

Basic

Expert

Web


WiFi

SSID	 YD9401
Password	12345678
Operating Mode	Access point (AP)
mDNS Name	 YD9401


DHCP

DHCP Server	Enabled
Start IP Address	192.168.16.100
End IP Address	192.168.16.200

YD9401 Info

Ethernet MAC Address	84:CC:A8:7A:0E:6F
Ethernet Link	100Mbps, Full Duplex
Firmware Version	V1.0.0
Temperature	 0,0 °C


IP Settings

IP Address	192.168.16.254
Subnet Mask	255.255.255.0
Default Gateway	192.168.16.254
Primary DNS Server	192.168.16.254
Secondary DNS Server	8.8.8.8
Hostname	 YD9401-WIFI


YD9401 Module Actions

Update Firmware


☐ + SPIFFS

 **Update**

Hardware Factory defaults

 **Reset**

Restart Module

 **Restart**






WiFi Props Properties


Basic Expert Web

WiFi

SSID  YD9401

Password 12345678

Operating Mode Access point (AP) ▾

mDNS Name  YD9401

DHCP

DHCP Server Enabled ▾

Start IP Address 192.168.16.100


End IP Address 192.168.16.200

YD9401 Info

Ethernet MAC Address 84:CC:A8:7A:0E:6F

Ethernet Link 100Mbps, Full Duplex

Firmware Version V1.0.0

Temperature  0,0 °C

IP Settings


IP Address 192.168.16.254

Subnet Mask 255.255.255.0


Default Gateway 192.168.16.254

Primary DNS Server 192.168.16.254

Secondary DNS Server 8.8.8.8


Hostname  YD9401-WIFI

YD9401 Module Actions

Update Firmware ☐ + SPIFFS  Update

Hardware Factory defaults

Restart Module  Reset



A fatal error occurred: Failed to connect to ESP32: Timed out waiting for packet header

